
SANDVIK SHARK (G.E.T.) PRODUCT WELDING DOCUMENTATION

WELD PROCEDURE SPECIFICATION WPS: SS-010 REV: 0 DATE: 31/12/13



SANDVIK SHARK (G.E.T.) PRODUCT WELDING DOCUMENTATION

WELD PROCEDURE SPECIFICATION

CONSUMABLE TREATMENT: Packaged spools in dry storage .

POST-WELD TREATMENT:

Spools on wire feeders to be dry and free of dirt/dust. Rusted wire to be discarded. Remove weld spatter, silicate patches and wire brush surface

WPS: SS-010 REV: 0 DATE: 31/12/13

Welder MUST visually examine weld to ensure absence of exposed porosity, absence of undercut, and to ensure that smooth transitions from weld face to material surfaces have been achieved.

Refer WPQR-SS005

SECTION 3.0

PROJECT SPECIFIC DATA

CLIENT NAME: SANDVIK SHARK (G.E.T.)

APPROVALS		
FABRICATOR:	FABRICATOR REPRESENTATIVE:	DATE:
CLIENT: SANDVIK SHARK (G.E.T.)	NAME: MARTEN KARLSSON, ENG. MANAGER	DATE:
THIRD PARTY: AWS(WA) - CONTRACTOR	NAME: IAN HENDERSON, IWE	DATE: